

# Valley Drive Abandoned Slurry

---

## Photo Log

---

Description: View of discarded refrigerators and appliances located on the site. Facing southeast

Category: Assessment Latitude: 48.1926319444444

Date Taken: 8/3/2022 Longitude: -114.396375916667

Tags:



Description: View of site facing southeast

Category: Assessment Latitude: 48.1926404166667

Date Taken: 8/3/2022 Longitude: -114.396402194444

Tags:



Description: View of the tank on site that has released or discharged hydrocarbon product into the right a way drainage pathway along West Valley Drive. Facing northeast

Category: Assessment Latitude: 48.1923925416667

Date Taken: 8/3/2022 Longitude: -114.396236972222

Tags:



Description: View of site facing northwest.

Category: Assessment Latitude: 48.1923347777778

Date Taken: 8/3/2022 Longitude: -114.395934444444

Tags:



Description: View of site facing north

Category: Assessment Latitude: 48.1922294444444

Date Taken: 8/3/2022 Longitude: -114.395782222222

Tags:



# Valley Drive Abandoned Slurry

---

## Photo Log

---

Description: View of tanks located on the northern portion of the site. Facing east

Category: Assessment Latitude: 48.1925963888889

Date Taken: 8/2/2022 Longitude: -114.396402222222

Tags:



Description: View of the right a way drainage pathway along the southwest property line. Facing southeast

Category: Assessment Latitude: 48.1925821277778

Date Taken: 8/2/2022 Longitude: -114.396454722222

Tags:



Description: View of the pathway that the hydrocarbon product that has been released or discharged from a tank into the right a way drainage pathway along West Valley Drive. Facing East

Category: Assessment Latitude: 48.1923773611111

Date Taken: 8/2/2022 Longitude: -114.396073611111

Tags:



Description: Close up view of the hydrocarbon product that has been released or discharged from a tank into the right a way drainage pathway along West Valley Drive.

Category: Assessment Latitude: 48.1923831666667

Date Taken: 8/2/2022 Longitude: -114.396062055556

Tags:



# Valley Drive Abandoned Slurry

---

## Photo Log

---

Description: View of the hydrocarbon product that has been released or discharged from a tank into the right a way drainage pathway along West Valley Drive.

Category: Assessment Latitude: 48.1923879583333

Date Taken: 8/2/2022 Longitude: -114.396068916667

Tags:



Description: View of the site facing northeast

Category: Assessment Latitude: 48.1922372055556

Date Taken: 8/2/2022 Longitude: -114.396014555556

Tags:



Description: View of the site facing North

Category: Assessment Latitude: 48.1921307111111

Date Taken: 8/2/2022 Longitude: -114.395788555556

Tags:



Description: Image of Site received by EPA on July 14, 2022 from party who reported the incident to the NRC.

Category: 00 Initial Report Latitude:

Date Taken: 7/14/2022 Longitude:

Tags:



Description: Image of Site received by EPA on July 14, 2022 from party who reported the incident to the NRC.

Category: 00 Initial Report Latitude:

Date Taken: 7/14/2022 Longitude:

Tags:





# Valley Drive Abandoned Slurry

---

## Photo Log

---

Description: Image of Site received by EPA on July 14, 2022 from party who reported the incident to the NRC.

Category: 00 Initial Report

Latitude:

Date Taken: 7/14/2022

Longitude:

Tags:



Description: Image of Site received by EPA on July 14, 2022 from party who reported the incident to the NRC.

Category: 00 Initial Report

Latitude:

Date Taken: 7/14/2022

Longitude:

Tags:



Description: Image of Site received by EPA on July 14, 2022 from party who reported the incident to the NRC.

Category: 00 Initial Report

Latitude:

Date Taken: 7/14/2022

Longitude:

Tags:



Description: Image of Site received by EPA on July 14, 2022 from party who reported the incident to the NRC.

Category: 00 Initial Report

Latitude:

Date Taken: 7/14/2022

Longitude:

Tags:



Description: Image of Site received by EPA on July 14, 2022 from party who reported the incident to the NRC.

Category: 00 Initial Report

Latitude:

Date Taken: 7/14/2022

Longitude:

Tags:



# Valley Drive Abandoned Slurry

---

## Photo Log

---

Description:	Image of Site received by EPA on July 14, 2022 from party who reported the incident to the NRC.		
Category:	00 Initial Report	Latitude:	
Date Taken:	7/14/2022	Longitude:	
Tags:			

---

