# U.S. ENVIRONMENTAL PROTECTION AGENCY POLLUTION/SITUATION REPORT Bearkamp Orphan Well Plug - Removal Polrep Initial and Final Removal Polrep



# UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Region V

Subject: POLREP #1

Documentation of Bearkamp Well Plugging (initial and final)

Bearkamp Orphan Well Plug

Z5L3

Ellsworth, OH

Latitude: 41.0366171 Longitude: -80.8383793

To:

From: Lori Muller, On-Scene Coordinator

**Date:** 8/2/2012

**Reporting Period:** 2/10/2012 to 4/23/2012

#### 1. Introduction

#### 1.1 Background

Site Number: Z5L3 Contract Number: D.O. Number: Action Memo Date:

 Response Authority:
 OPA
 Response Type:
 Emergency

 Response Lead:
 EPA
 Incident Category:
 Removal Action

NPL Status: Non NPL Operable Unit:

 Mobilization Date:
 4/23/2012
 Start Date:
 4/24/2012

 Demob Date:
 4/24/2012
 Completion Date:
 4/24/2012

CERCLIS ID: RCRIS ID:

ERNS No.: State Notification: State Referral

FPN#: E12502 Reimbursable Account #: 2/V/SZ/172/95/0/E12502/74100/Z5L3

#### 1.1.1 Incident Category

Time Critical Removal Action to plug a leaking, abandoned orphan well.

#### 1.1.2 Site Description

The Ohio Department of Natural Resources, Division of Mineral Resources, Oil & Gas Permitting Section, requested assistance from USEPA in evaluating a leaking oil well (the Bearkamp Well) near Ellsworth, Mahoning County, Ohio.

The well is an orphan well and the state has found no records identifying responsible parties to properly plu g the well.

On April 11, 2011, OSC Muller inspected the well site and found that the well was discharging oil to the Meander Creek which leads to the Little Beaver Creek, and eventually, the Ohio River.

OSC Muller made the determination that the well should be properly plugged to eliminate the on-going dicharge from the well.

ODNR agreed to undertake the plugging operations of the well through the Pollution Removal Funding Authorization (PRFA) process. The state has emergency funds to plug the well, but would require reimbursement from the Fund Center.

# 1.1.2.1 Location

The well is located on the Hornberger's property (LAT: 41.039420, LON: -80.831980) in Ellsworth Township, Mahoning County, Ohio.

#### 1.1.2.2 Description of Threat

The abandoned well was discharging oil to Meander Creek, a tributary to the Ohio River.

# 1.1.3 Preliminary Removal Assessment/Removal Site Inspection Results

On April 11, 2011, OSC Muller inspected the well site and found that the well was discharging oil to the

#### 2. Current Activities

#### 2.1 Operations Section

#### 2.1.1 Narrative

#### 2.1.2 Response Actions to Date

The contractor for ODNR plugged the well on April 23-24, 2012. The contractor plugged the well under the supervision of an ODNR Field Inspector and according to the Scope of Work (SOW) attched to the PRFA posted in the documents section of this website.

#### 2.1.3 Enforcement Activities, Identity of Potentially Responsible Parties (PRPs)

Orphan well- no PRPs.

#### 2.1.4 Progress Metrics

Waste Stream	Medium	Quantity	Manifest #	Treatment	Disposal

#### 2.2 Planning Section

#### 2.2.1 Anticipated Activities

none

## 2.2.1.1 Planned Response Activities

none

#### 2.2.1.2 Next Steps

No further response actions - well has been plugged.

#### 2.2.2 Issues

none

#### 2.3 Logistics Section

N/A

### 2.4 Finance Section

No information available at this time.

#### 2.5 Other Command Staff

N/A

#### 3. Participating Entities

N/A

# 4. Personnel On Site

N/A

# 5. Definition of Terms

N/A

# 6. Additional sources of information

N/A

#### 7. Situational Reference Materials

N/A