

Louisa Acme Well Site

Monitoring Well Results Summary January 2011

All results are in *microgram/liter*

	MW-01	MW-02	MW-03	MW-04
1,1-Dichloroethane			0.54	
Trans-1,2-dichloroethene			0.66	
Cis-1,2-Dichloroethene			14	
Trichloroethene		2.6	45	
Tetrachloroethene		370	390	

MW-01 - Monitoring Well #1 – northernmost well

MW-02 – Monitoring Well #2 – north of western end of East Pond

MW-03 – Monitoring Well #3 – south of western end of East Pond

MW-04 – Monitoring Well #4 – Western side of property east of gravel parking lot